













UNLESS OTHERWISE SPECIFIED LEADING DIMENSIONS ARE INCHES DIMENSIONS IN [] ARE MILLIMETERS

TOLERANCES:

FRACTIONS .X = ±.2 [5.08] $.XX = \pm .02$ [.51] ± 1/32 .XXX = ±.005 [.13] ANGLES ± 1°

CABLE LENGTH (L) TOLERANCES:

L ≤ 12 [305] = +1 [25] / -0 12 [305] < L ≤ 60 [1524] = +2 [51] / -0 60 [1524] < L ≤ 120 [3048] = +4 [102] / -0 120 [3048] < L ≤ 300 [7620] = +6 [152] / -0 300 [7620] < L = +5%L / -0

Α

ALL DIMENSIONS SHOWN ARE FOR REFERENCE ONLY

Show Me CABLES

an INFINIT® brand

115 Chesterfield Industrial Blvd., Chesterfield, MO 63005

Phone: 1.888.519.9505 Fax: 1.888.519.9515 Website: www.ShowMeCables.com

E-mail: CustomerService@ShowMeCables.com ITEM NO. SIZE CAGE CODE DRAWN BY

SCALE

N/A

THIRD-ANGLE PROJECTION

THE INFORMATION AND DESIGN IN THIS DOCUMENT IS THE PROPERTY OF

SHOWMECABLES, INC ALL RIGHTS RESERVED.

REV 3SVT8 DZINN SMCM3406-B-P-A Α

THESE COMMODITIES, TECHNOLOGY OR SOFTWARE WERE EXPORTED FROM THE UNITED STATES IN ACCORDANCE WITH THE EXPORT ADMINISTRATION REGULATIONS. DIVERSION CONTRARY TO U.S. LAW PROHIBITED.

