















UNLESS OTHERWISE SPECIFIED LEADING DIMENSIONS ARE INCHES DIMENSIONS IN [] ARE MILLIMETERS

TOLERANCES:

FRACTIONS .X = ±.2 [5.08] $.XX = \pm .02$ [.51] ± 1/32 .XXX = ±.005 [.13] ANGLES ± 1°

CABLE LENGTH (L) TOLERANCES:

L ≤ 12 [305] = +1 [25] / -0 12 [305] < L ≤ 60 [1524] = +2 [51] / -0 60 [1524] < L ≤ 120 [3048] = +4 [102] / -0 120 [3048] < L ≤ 300 [7620] = +6 [152] / -0 300 [7620] < L = +5%L / -0

ALL DIMENSIONS SHOWN ARE FOR REFERENCE ONLY

Show Me CABLES

an INFINIT® brand

115 Chesterfield Industrial Blvd., Chesterfield, MO 63005

Phone: 1.888.519.9505 Fax: 1.888.519.9515 Website: www.ShowMeCables.com

E-mail: CustomerService@ShowMeCables.com ITEM NO. SIZE CAGE CODE DRAWN BY

SHOWMECABLES, INC ALL RIGHTS RESERVED. SCALE

N/A

3SVT8 DZINN

Α

SMCM3406-G-P

REV

Α

THIRD-ANGLE PROJECTION

THE INFORMATION AND DESIGN IN THIS DOCUMENT IS THE PROPERTY OF

THESE COMMODITIES, TECHNOLOGY OR SOFTWARE WERE EXPORTED FROM THE UNITED STATES IN ACCORDANCE WITH THE EXPORT ADMINISTRATION REGULATIONS. DIVERSION CONTRARY TO U.S. LAW PROHIBITED.

